



- LEGEND

1. Existing clubhouse
2. New ramp and connecting concrete pathway 1.5m wide, to AS1428.1
3. New asphalt carpark area (46 spaces) with kerb and concrete edging
4. Two accessible carparking spaces with improved access to clubhouse
5. New shade trees
6. Existing path to remain
7. Wheel stops
8. Existing trees to be removed due to poor condition
9. Grassed area to replace pavement in front of clubhouse
10. 300mm deep concrete perimeter edging to protect pavement
11. Recently upgraded on-site sewage management system

- MAP

